Typical Site Investigations for a GHG Subsidence Claim





PHOTOGRAPH 01:

This shows a typical trial hole, exposing the underside of the foundations (marked with the hand trowel).



PHOTOGRAPH 02:

This photograph shows a trial hole exposing the existing foundations and the top of the bore hole that is hand driven at the bottom of the hole.



PHOTOGRAPH 03:

This photograph shows the type of CCTV equipment used to inspect the drains.



PHOTOGRAPH 04:

This photograph shows metal 'demec' studs fitted to an external wall. These studs are used to accurately measure any changes in the cracks over time